

Get an idea of our prices.

<i>Problem</i>	<i>Fixable?</i>	<i>Price (£)</i>
Golf-bag pocket or main zip does not close or one side has come off the slider or/and some teeth are detached from the material of the zip	yes	£28-34 for one slider to put back on track or replace, plus re-attach teeth on the material (up to 1 inch)
Zip coil detached from material and/or stretched	yes	15 - 25 up to 2inches in length
Zip does not stay closed	yes	jacket =20-28 , boot =22-28, bag =20-28 suitcase =24-30 (depending on size and type of runner)
Zip is stuck and the runner just won't move	yes	16 - 28
One of the sides of the zip has come away	yes	jacket =20-30 , boot =22-28, bag =20-30 suitcase =24-32 (depending on size and type of runner and difficulty)
Insert pin damaged , on open ended zips	yes	24 - 28 to rebuild material around pin
End part of the open ended zip on a jacket is broken or worn (retainer box or insertion pin)	yes	22-28 depending on the actual problem. We can add missing retainer box or insertion pin, rebuilding the cloth around it etc. Changing a jacket zip is sometimes impossible, so fixing the existing one is the way.
Metal teeth are missing on a metal zip	yes	Please send us a picture to see the problem.
Plastic teeth are missing on a metal zip	yes	Please send us a picture to see the problem.